UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA	Doc	nifest cument No.		innet		he shaded ar
Generator's Name and Mailing Address	[W.A.D.9.8.0.7]				ate Manifest D		
Alaskan Copper Works P.O. Box 3546, Seattle,	WA 96124 20	4 he Pagere 16-647-89 63	<b>.</b>		ate Generator's		
Generator's Phone ( 206 ) 382-							
Transporter 1 Company Name	14 ( 6.	US EPA ID Numi			ate Transporte ansporter's Ph		
Transporter 2 Company Name	8.	US EPA ID Numi		E. St	ate Transporte	r's ID	**************************************
Deleted Fellin News 1 Str. Add.					ansporter's Pho	- The Manney of the Line of the	
Designated Facility Name and Site Address World Resources Company	ess 10.	US EPA ID Numb	per	G. St	ate Facility's ID		e vjesset
8113 West Sherman Street Tolleson, Arizona 85353-		D.9.8.0.7.3	5 5 0 0	H. Fa	cility's Phone	800-9	72-1955
. US DOT Description (Including Proper S	hipping Name, Hazard Cla	ass and ID Number)	12. Cont	ainers	13. Total	14. Unit	I. Waste No
HM			No.	Type	Quantity	Wt/Vol	
RQ, Hazardous was (F008), 9, NA3077		6.,	002	C F	Ø3.24.9	Р	F006
RQ; Hazardous was (D007), 9; NA307	<del>sto, aclid, n.o.</del> 7 <del>, III</del> G	•		D M		8	D007*
And the second contract of the second contrac	nghaga nagaragangangangangangangangangangangangangan	one integration of the contract of the contrac	ing and some some	and the same of th		4. 61	
Additional Descriptions for Matérials Lish carding the burder estimate 12.23 to S. Sirvingaments constroint and Regulatory	roint sero commens re nation Policy Branch, PM 0 and to the Olice of Into	or freatment, storage ig and reviewing fine rden, to Chfel, infort shington, C.C. 2046i Washington, D.C. 2	id completii ing folk bur et SVI We	dala, al or redul M Stre	ons, gathēring 1 suggestions ( 20 Anency 401	instructi includint Pentantii	Listed Above
Special Handling Instructions and Addit 4 Hour Emergencey Response Use CHEMIREC company code CHEMIREC COMPANY CODE CHEMIREC COMPANY CODE CHEMIRECTOR'S CERTIFICATION: I hereby declar proper shipping name and are classified, packed,	se: 1-800-424-93  *WORR*) Wear  re that the contents of this cons	gloves & gor	curately descr	ibed abov	e by	er #20	6-648-84
according to applicable international and national If I am a large quantity generator, I certify that economically practicable and that I have selectfuture threat to human health and the environment the best waste management method that is available.	government regulations.  It I have a program in place to cted the practicable method of ment; OR, if I am a small qua	o reduce the volume ar if treatment, storage, or antity generator, I have r	nd toxicity of disposal curi	waste gei rently ava	nerated to the de	h minimize	s the present
7Printed/Typed Name 1EX/NO Thompson		Signature		لتستنسست فيست			onth Day
	ceipt of Materials		<i>y</i>			<u> </u>	ब भारत लंह
7度から トゥーラング Transporter 1 Acknowledgement of Rec		Signature	50 P 10				onth Day
Transporter 1 Acknowledgement of Reconstruction Printed/Typed Name		I dies.	Mille				J 140
Transporter 1 Acknowledgement of Rec Printed/Typed Name	eipt of Materials	Signature	MULLE			М	
Transporter 1 Acknowledgement of Reconstruction Printed/Typed Name  Printed/Typed Name  Printed/Typed Name  Transporter 2 Acknowledgement of Reconstruction	eipt of Materials		m Hp			M	


Signature

Style CF 17 LABEL MASTER ® (800) 621-5808 www.labelmaster.com

EPA Form 8700-22 (Rev. 9-88) Previous editions are obsolete.

Month Day

**GENERATOR COPY** 



Printed/Typed Name

# Material Safety Data Sheet

## F006 Recyclable Material (Filter Cake)

Pecycler's Facility Name and Ste Address:

World Resources Company

8113 West Sherman Street Phoenix, Arizona 85043-3000

Fax: 623-936-9164 Tel: 602-233-9166

Issued: 8/7/90 Revised: 8/5/99 DLS

Call CHBMTREC only in the event of emergencies during shipping that involve a spill, leak, fire, or accident (all calls are recorded)

For Emergencies During Shipping in the USor Canada, Day or Night, Call: CHEM TREC 800-424-9300 (Use CHEM TREC Company Code "WORR") For calls from other countries call: 703-527-3887 Collect

#### Section 1

EPA Waste Classification: F006

Generic Name: Electroplating/Metal-Finishing Wastewater Treatment

Sudge

Chemical Family: Metallic (Hydroxide) Precipitates

Synonym: Non-ferrous Metal Hydroxide Filter Cake

## Material Identification

DOT Shipping Name: RQ, Hazardous waste solid, n.o.s. (F006)

DOT Hazard Class: 9; Packing Group: Ill DOT Identification Number: NA 3077

Guide 171 of the North American Emergency Response Guidebook

Applies

Section 2				Hazardous Ingredients
Ingredient:	CAS Number:	Content %:	ACGIH-TLV	Toxicology: (rat, oral)
Copper Hydroxide	20427-59-2	0 - 30	1.0 mg/m <sup>3</sup> (Dust)	LD-50 1.000 m g/ kg
Nickel Hydroxide	12054-48-7	0 - 15	1.0 mg/m <sup>3</sup> (Dust)	LD-50 1,500 mg/kg
Calclum Hydroxide	1305-62-0	0 - 15	5.0 mg/m <sup>3</sup> (Dust)	LD-50 7,340 mg/kg
Amorphous Silica	61790-53-2	0 - 10	10.0 mg/m <sup>3</sup> (Dust)	LD-50 Not Determined

#### Editor G

Description: Solid, Clay-like, Gray/ Green to Brown.

Water Content 30 - 80%

Specific Gravity: 2.5 To 3.5

Solubility: Insoluble in Water

Incompatible Reactivity: None Known

Vapor Pressure: Insignificant Stability: Avoid Contact With Acids Polymerization: Will Not Occur

Physical And Reactivity Data Density 50 to 90 lbs/cu ft

Boiling Point: Above 2600°C Melting Point: Above 1800°C

pH: 7.0 to 10.0

#### Section:4

Flashpoint: Nonflammable

Special Firefighting Procedures: None

Product Decomposition (Due To Fire Or Explosion): None

Oxidation: Non-oxidizing

Explosive: Non-Explosive

NEPA Fire Diamond



Fire And Explosion Data

Listed Carcinogen component: Nickel

Toxicology: See Sec. 2

Route of Entry: Inhalation and Ingestion Health Ellects And First Aids

## Section 6

Inhalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms.

Ingestion: Rare in industry, Induce vomiting (do not induce vomiting or give a liquid to an unconscious person) and call a physician.

Eyes: Dust may irritate eyes. Wash with copious amounts of water for 15 minutes, if effects persist, call a physician.

Skin: Dust may irritate skin, causing forms of eczema. Wash with soap and water.

Long-Term: The effects of long-term chronic overexposure may affect the following target organs or body systems--blood.

digestive, respiratory, lungs, liver, kidneys and skin.

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent

kidney damage and metal-sensitive skin or skin lesions.

#### Section 7

Handling: Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment (PPE) be used by personnel who will come in contact with the material. The PPEshould include eye protection, respirator and gloves.

Storage: Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled to avoid inhalation or ingestion. Store in a dry area under cover to protect from rain.

Spills: Use cleaning procedures that avoid creating excessive dust. Vacuum when possible. Package material and ship to World Resources Company at above address.

#### Section 8

Respiratory Protection: NIOSH-MSHA approved respirators as required. Other Protective Equipment: Coveralls are recommended, but not required.

Eye Protection: Safety Glasses recommended. Hand Protection: Gloves recommended.

#### Section 9

# Generator's Verification

This MSDS is provided solely for informational purposes and no warranty or responsibility is extended even though reasonable precautions have been taken in the preparation of the data contained for this recyclable material. To the best of my knowledge this MSDS describes the recyclable material listed on the attached Manifest Number: 22002 Telephone: 206-382-8379

Company Name and Address: Alaskan Copper Works

P.O. Box 3546, Seattle, WA 98124

Sgnature⊊



# LAND DISPOSAL RESTRICTION NOTICE

F006

EFFECTIVE 11/09/98

[A copy of this Notice must be retained by the Generator for at least three (3) years, pursuant to U.S. EPA Regulation 40 CFR §268.7(a)(8). Moreover, the Generator should check the hazardous-waste regulations of his/her own State, inasmuch as, if there is a State analogue to the federal regulation, it may require a longer retention time, such as five (5) years. It should also be noted that the federal regulation—and, typically, State analogues as well—requires the retention period to be extended further in specified cases.]

To:	WORLD	RESOURCES COMPANY		8113 W	est Sherman Street,	Phoenix AZ 85043-3000
From:	COMPANY NAME:		COMPANY	ADDRESS:		
	Alaskan	Copper Works		P.O. Box	3546, Seattle, WA 98124	
	NIFEST	02002		DATE OF SHIPMENT		
		it of material is subject to	EPA Mate Numbe		Treatability Group	CFR Reference for Treatment Standards
	-	sal restrictions of 40 CFR applicable land disposal	F006		non-wastewater	40 CFR §268.40
		information, provided in				
		th 40 CFR §268.7(a)(2), is as shown in this table:				
SIG	NATURE:	Sul Sie		TITLE:	ENVIRO. ASST	
NAME	PRINTED:	GERDOO A. Thom	Pso-1	DATE:	3-6-02	

# Instructions for Completion of this Land Disposal Restriction Notice [LDRN]

This LDRN has been prepared based on a listed material--F006--as the primary designation of the material. This designation is based on information furnished by the Generator of the material. While it is believed to be accurate, it is the Generator's responsibility to determine whether his/her material is restricted from land disposal, and to correctly complete the LDR Notice [as stated in 40 CFR §268.7(a)(2)].

An F006 designation on the LDRN includes the following constituents: cadmium [D006], chromium [D007], lead [D008], silver [D011], cyanide, and nickel. However, the designation does not include arsenic [D004], barium [D005], mercury [D009], or selenium [D010]. If your F006 material contains any of those four constituents not included in the F006 designation, then use the following instructions.

In determining the need for any additional entries on the LDRN for the F006 material, the levels of arsenic, barium, mercury and selenium must be examined to determine if the levels equal or exceed the threshold concentrations of constituents for the Toxicity Characteristic limit as identified in 40 CFR §261.24 (Table 1), as shown in the left-hand column of the table below [as stated in 40 CFR §268.9].

If (after testing or based upon the generator's knowledge of the material) each metal level does not equal the Toxicity Characteristic level shown below, then no additional entry is required on the LDR Notice. If the level is known to be or determined to be equal to or above the limit shown below for any of these metals, then the appropriate information corresponding to that individual metal (in the right-hand column below) must be added to the LDR Notice.

	E INFORMATION CHARACTERISTIC	APPROPRIATE ENTRY ON LDR NOTICE				
Metal	Concentration Level	EPA Material Number	Treatability Group	CFR Reference for Treatment Standards		
ARSENIC	5.0 mg/l	D004	non-wastewater	40 CFR §268.40		
BARIUM	100 mg/l	D005	non-wastewater	40 CFR §268.40		
MERCURY	.02 mg/l	D009	non-wastewater	40 CFR §268.40		
SELENIUM	1.0 mg/l	D010	non-wastewater	40 CFR \$268.40		

D1994 by WORLD RESOURCES COMPANY, Revised 11/08/98, As ingits reserved AZERTONET

**FOOG GENERATORS** 

## MATERIAL IDENTIFICATION

DOT BASIC SHIPPING DESCRIPTION AND TECHNICAL NAME: Hazardous waste, solid, n.c.s., (F006), 9, NA3077, III

NORTH AMERICAN EMERGENCY RESPONSE

# TAKEN FROM GUIDE 171 OF THE NORTH AMERICAN EMERGENCY RESPONSE GUIDEBOOK

(Underlined text applies directly to the material listed above)

#### POTENTIAL HAZARDS

#### FIRE OR EXPLOSION

- Some may burn, but none ignite readily.
   Some may polymenze (P) explosively when heated or involved in a fire.
- 3. Containers may explode when heated.
- 4. Some may be transported hot.

#### HEALTH

- 1.Inhalation of material may be harmful.
- 2. Contact may cause burns to skin and eyes.
- 3.Innaiation of Aspestos dust may have a damaging effect on the lungs.
- 4. Fire may produce irritating, corrosive and/or toxic gases.
- Runoff from fire control may cause pollution.

#### PUBLIC SAFETY

- CALL CHEMTREC at 1-300-424-9300 FOR EMERGENCY ASSISTANCE (Use CHEMTREC Company Code "WORR")
- 2. Isolate spill or leak area immediately for at least 10 to 25 meters (30-30 feet) in all directions.
- Keep unauthorized personnel away.
- 4. Stay upwind.

#### PROTECTIVE CLOTHING

- 1. Wear positive pressure self-contained breathing apparatus (SCBA).
- 2. Structural firefighters' protective cothing will only provide limited protection.

#### EVACUATION

1.If tank, rail car or tank truck is involved in a fire, ISOLATE for 800 meters (1/2 mile) in all directions; also, consider initial evacuation for 800 meters (1/2 mile) in all cirections.

## FIRE .

#### **EMERGENCY RESPONSE**

#### Small Fires

1. Dry chemical, CO2 water scray or requiar foam.

#### Large Fires:

- 1. Water spray, fod or requiar foam
- 2. Move containers from fire area if you can do it without risk.
- 3.Do not scatter spilled material with high pressure water streams.
- 4. Dike fire-control water for later disposal.

## Fire involving Tanks:

- 1. Cool containers with flooding quantities of water until well after fire is out.
- 2. Withdraw immediately in case of rising sound from venting safety devices or discoloration of tank.
- 3.ALWAYS stay away from the ends of tanks.

#### SPILL OR LEAK

- 1.Do not touch or walk through spilled material.
- 2.Stop leak if you can do it without risk 3.Prevent dust cloud.
- Avoid inhalation of asbestos dust.

#### Small Dry Spills

- 1. With clean shovel, place material into clean, dry container and cover loosely; move containers from spiil area. Small Spills
- 1. Take up with sand or other concompustible apsorpent material and place into containers for later disposal. Large Spills
- Dike far anead of liquid spill for later disposal.
   Cover powder spill with plastic sneet or fam to minimize spreading.
- 3. Prevent entry into waterways, sewers, basements or confined areas.

#### FIRST AID

- 1.Move victim to fresh air.
- Cail emergency medical care
- 3. Apply artificial respiration if victim is not breathing.
- 4. Administer oxygen if breathing is difficult.
- 5. Remove and isolate contaminated clothing and snoes.
- 6.In case of contact with substance immediately flush akin or eyes with dunning water for at least 20 minutes.
- 7. Ensure that medical personnel are aware of the material(s) involved, and take precautions to protect themselves.